Message

From: Praskins, Wayne [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP

(FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=4F47BC0A2C2E42A98347D59CD1A98B19-WPRASKIN]

Sent: 5/24/2021 9:00:07 PM

To: Roddy, Elizabeth A CIV USN NAVFAC SW SAN CA (USA) [elizabeth.roddy@navy.mil]; juanita.bacey@dtsc.ca.gov; Han,

Terry@CDPH [terry.han@cdph.ca.gov]

CC: Stoick, Paul T CIV USN NAVFAC SW SAN CA (USA) [paul.stoick@navy.mil]

Subject: RE: Parcel G TU-79 Sr-90 Results

Liz -

Do you consider the Parcel Sr-90 results for the two samples that exceeded the RG and the 8 additional aliquots preliminary or final (i.e., will they undergo any further review or validation)?

Wayne Praskins | Superfund Project Manager U.S. Environmental Protection Agency Region 9 75 Hawthorne St. (SFD-7-3) San Francisco, CA 94105 415-972-3181

From: Roddy, Elizabeth A CIV USN NAVFAC SW SAN CA (USA) <elizabeth.roddy@navy.mil>

Sent: Tuesday, May 11, 2021 4:56 PM

To: Praskins, Wayne <Praskins.Wayne@epa.gov>; juanita.bacey@dtsc.ca.gov; Han, Terry@CDPH

<terry.han@cdph.ca.gov>

Subject: Parcel G TU-79 Sr-90 Results

All,

As promised attached you will find the lab data package for TU-124. The systematic samples are included in J40475-1 and the Sr-90 result for systematic sample -001 is shown on Page 14. The data for the four additional aliquots are included in J40475-2.

As discussed a complete RSY Data Package will be submitted once pending removal boundary soil sample's analytical results are available.

Very Respectfully,

Liz Roddy Remedial Project Manager NAVFAC BRAC PMO West 33000 Nixie Way Bldg. 50, Floor 2 San Diego, CA 92147 (619) 524-5755 elizabeth.roddy@navy.mil